INDUSTRY SERVICES PO Box 7302 Madison, WI 53707-7302 608) 266-2112 FAX (608) 267-9723 Contact Through Relay

Scott Walker, Governor Laura Gutiérrez, Secretary



Customer ID No: 257936 June 21, 2017

CITY OF MANITOWOC - MUNICIPAL CLERK 900 QUAY ST MANITOWOC, WI 54220-4543

RE: NOTIFICATION OF INSPECTION DUE

CROSS CONNECTION CONTROL DEVICE

Our records indicate that the cross-connection control device(s) or assembly(s) listed below are past due for the periodic test by a department-registered Cross-Connection Control Device Tester. The due dates are the expiration dates listed.

A cross-connection control device or assembly is a mechanical valve that protects the potable water supply system from contamination. Since a physical connection between the potable water supply and substances of either unknown or questionable quality exists in the facilities listed below, a cross-connection control device or assembly was/is required. Each installed device or assembly must be tested at least annually to ensure that it continues to function as designed.

It is the owner's responsibility to have a performance test conducted by a department registered Cross-Connection Control device tester prior to the device or assembly being put into service and at least annually thereafter. Also, the device or assembly must be tested whenever repairs or replacements occur. Every time a test is performed, a test report must be submitted to this office with a \$30 check for processing made payable to "Industry Services", or the test results can be entered online at a reduced fee of \$20 per report.

All CCC device testers must be registered by Industry Services. In order to find a registered tester, contact any independent CCC testing agency or your local plumbing contractor.

If the required test has been completed, but the report was not sent in, please attach the report to this letter and return to the above address. Please disregard this notice if your report is already in the mail. If the device or assembly was never installed or has since been removed from service*, please notify this office in writing as to the reason(s) for not installing or removal of the device or assembly. If you have difficulty identifying the plumbing device, please contact a department registered Cross-Connection Control Device Tester or your local plumbing inspector for assistance.

*Cross Connection Control devices or assemblies taken out of service must be disconnected and physically removed from the water line. The department must also be notified in this case.

Cross Connection Control Device(s):

Regulated Object ID	Regulated Object Description Section Cross Connection Control Devices
1460757	Tag No.: 1460757; Plumbing 2655 S 35th St, Manitowoc, 54220; Site: Manitowoc County, City of Manitowoc; Location on Property: S Wall By Mtr In Main Garage Last Investigation Date: 5/26/2016 15:15:00; Current PTO Expiration Date: 5/26/2017; Serial #: N1-0864

A CONTRACTOR OF THE STATE OF TH Burn Walter 建物性 人名德西林格克尔 第二次的 SECULLARIA SE CONTRACTOR O And the state of till og kommen skiller og til here kræde og til koller figt stolkere gælde og stolke hellet for Hellet og til stolker kræde og til til stolker til skoller filter og til ett blet kræde og koller til ett blet Hellet og til skale kræde og til til skale Hellet og til kræde til skale og til skale on the appearant of the action of a training of the action to the action of the action ကန္တာမွာ နေလာရုံးနေတြသည်။ ကိုဆိုဆိုသည် ၁၈၁ ခုဆိုသည်။ ကိုသည်။ ကန္တာကိုသို့မြန်မာ မည့္ခုတည်များမွာ အျဖစ္သည်။ ၁၈၁၈ and the research of arm the conservation of the second and the following the first of the control of the control of the control of the first of the control of the con Control of the second on the control of the state of the control of the c and the state of the control of the state of t The state of the state a tantan kan tantatan tanggala dikepitan menjalah dikeberta, alimbig filipikan diangkapan selaji Page Asectel School Space gradiente in Springer au de la company Company of the second consists Land rest year Therefore Single

CROSS CONNECTION CONTROL DEVICE

Our records indicate that the cross-connection control device(s) or assembly(s) listed below are past due for the periodic test by a department-registered Cross-Connection Control Device Tester. The due dates are the expiration dates listed.

A cross-connection control device or assembly is a mechanical valve that protects the potable water supply system from contamination. Since a physical connection between the potable water supply and substances of either unknown or questionable quality exists in the facilities listed below, a cross-connection control device or assembly was/is required. Each installed device or assembly must be tested at least annually to ensure that it continues to function as designed.

It is the owner's responsibility to have a performance test conducted by a department registered Cross-Connection Control device tester prior to the device or assembly being put into service and at least annually thereafter. Also, the device or assembly must be tested whenever repairs or replacements occur. Every time a test is performed, a test report must be submitted to this office with a \$30 check for processing made payable to "Industry Services", or the test results can be entered online at a reduced fee of \$20 per report.

All CCC device testers must be registered by Industry Services. In order to find a registered tester, contact any independent CCC testing agency or your local plumbing contractor.

If the required test has been completed, but the report was not sent in, please attach the report to this letter and return to the above address. Please disregard this notice if your report is already in the mail. If the device or assembly was never installed or has since been removed from service*, please notify this office in writing as to the reason(s) for not installing or removal of the device or assembly. If you have difficulty identifying the plumbing device, please contact a department registered Cross-Connection Control Device Tester or your local plumbing inspector for assistance.

*Cross Connection Control devices or assemblies taken out of service must be disconnected and physically removed from the water line. The department must also be notified in this case.

Cross Connection Control Device(s):

Regulated	Regulated Object Description Section
Object ID	Cross Connection Control Devices
	Cross Connection Control Devices

1336287	Tag No.: 1336287; Plumbing Facility: Manitowoc Public Safety Bldg, 911 Franklin St, Manitowoc, 54220; Site: Manitowoc County, City of Manitowoc; Location on Property: Room 230 Last Investigation Date: 6/14/2016 10:28:00; Current PTO Expiration Date: 6/14/2017; Serial #: 329702
1336291	Tag No.: 1336291; Plumbing 911 Franklin St, Manitowoc, 54220; Site: Manitowoc County, City of Manitowoc; Location on Property: Boiler Room 220 Last Investigation Date: 6/14/2016 10:00:00; Current PTO Expiration Date: 6/14/2017; Serial #: 329683
1336292	Tag No.: 1336292; Plumbing Facility: Manitowoc Public Safety Bldg, 911 Franklin St, Manitowoc, 54220; Site: Manitowoc County, City of Manitowoc; Location on Property: Room 230 Last Investigation Date: 6/14/2016 10:15:00; Current PTO Expiration Date: 6/14/2017; Serial #: 329698
1335051	Tag No.: 1335051; Plumbing Facility: Manitowoc Public Safety Bldg, 911 Franklin St, Manitowoc, 54220; Site: Manitowoc County, City of Manitowoc; Location on Property: Room 162 Right Of Door Last Investigation Date: 6/14/2016 09:40:00; Current PTO Expiration Date: 6/14/2017; Serial #: 642872

and the second

ေသည့် အေရြးမေရးမေရးမေရးမေရးသည်။ မြန်မာသည် သို့သည်။ သို့သည် မေရာက် သောများသည်။ မေရာက်လိုင်လည်း သင်္ကာလေးသည်။ လေသည် မေရာက်ကြီး လေးအောင်မေရေးမေရာက်မှာ သင်္ကာမေရေးမေရ မေရေးမေရေးမေရာက် လေးသည်။ လေးသည် မေရာက်မေရေးမေရေးမေရေးမေ သင်္ကာမေရးမေရာက် ကို မိုမေရတည်းသည်။ မေရာကျွန်းမေရေးမေရာက်များသည်။ မေရာက်များသည်။ မေရာက်များသည်။ မေရာက်များများ

the Control of North Bright Control of States of States and States of States and States and States of the States o

and the property of the support of the second of the secon

The state of the s

of the second second

ा है कि को राज्य के हैं कि है। अब राज्य के के कम्म के की है है है है जो की रेजिस के हैं है जो की है जो की की है

ారు. ప్రాంతి ప ముగ్రాంతి ప్రాంతి ప్రాం ప్రాంతి ప్రాంత ప్రాంతి ప్రాంతి

Company of the Company of the Company

THE EDUCATION OF THE PARTY OF T

and the first of the second second

The state of the s

The Committee of the American Committee of the Committee

Control of the Contro

n production of the second The second of th